From: Stevenson, Allan (DPH)

Sent: Tuesday, March 18, 2008 10:50 AM

To:
Nassif, Julianne (DPH); Pribeck, Kristen (DPH)
Cc:
Hanchett, James (DPH); Salem, Sharon (DPH)
Subject:
FW: Bench Repair/Exchange Paperwork

Attachments: 08-21-07_US-NAFRC_3in1.pdf

Hi Julie,

Attached is the quote to repair the injector tower (model G2613A) for our GC/MS. Basically what it says is that a repair costs \$905 plus \$185 for a loaner and shipping. An exchange for a rebuilt injector is \$1485 including shipping. Last time it broke we did the repair.

The injector is working intermittently right now.

Cam

From: support@agilent.com [mailto:support@agilent.com]

Sent: Tuesday, March 18, 2008 10:21 AM

To: Stevenson, Allan (DPH)

Subject: Bench Repair/Exchange Paperwork

Allan,

Please fill out the forms and return to the Field Repair Group as per the instructions in the attached paperwork.

Service Request Numbers: 1-1244716933.

If you need more information, please call 800-227-9770 and choose Option 3 for Instrument Service and Support.

Ed DiEgidio Customer Support Engineer Tel (800) 227-9770, option 3

Email: support@agilent.com

| × | The ledded issign current bir displayed. The fills may have been moved, reviewed, or debted. Verify that the birk points to the correct file and location. |
|---|--|
| | |
| | |

NOTE: this e-mail may contain confidential information and is meant for the intended recipient(s) only. If you are not an intended recipient or someone authorized to receive e-mail on behalf of an intended recipient, please reply to the sender that the email was misdirected and delete the email